



# PLATE NOTES

2) Do not terminate top end of these cables. Also, these cables total length

3) Do not terminate top end of this cable. This cables total length is

length and then mark out lengths -Measurements are to the top of the lath board when assembling -See supplemental excel spreadsheet -Dashed lines indicate lath board seams (see WAL-1.0 for layout) -Cables attach to batten with trim

#	DESCRIPTION	DATE
1	Initial Draftings	06/05/2019
2	Shop Drawings	07/14/2019
3		
4		
5		



Assistant Technical Director

1 /2"	= 1'0"	NIC MAN	
1/ 2	1.0	NSMW	
BLULT/SIGNED OFF BY			





